

## DAILY REPORT OF FIELD OBSERVATIONS

Service Date: 07/10/2024

**Ninyo & Moore**

Geotechnical and Environmental Sciences Consultants

1991 East Ajo Way, Suite 145

Tucson AZ 85713

520.577.7600 | [www.ninyoandmoore.com](http://www.ninyoandmoore.com)

**Project Name:** Rancho Vistoso Valley Vista Sewer Repair  
**Project Address:** 601 E. Kalalau Dr.  
Oro Valley AZ 85755  
**Client:** Pima County  
**General Contractor:** Hunter Contracting  
**Approved Documents:**

**Project Number:** 608157001  
**Jurisdiction:**  
**Permit:**  
**Plan File No.**

### Summary of Field Services:

Arrived on site and talked to Eric on what needed testing.

No density or slurry tests were necessary for today due to finding utilities with pump took longer than planned.

Finished paperwork before leaving site.

**Weather:** Sunny, Calm, Dry, Low Humidity

### SIGNATURES

Start Time	Stop Time	Standard Hours	Overtime Hours	Travel Hours	Total Miles		
07:00	14:00	7	-	2	44	Edwin Gonzalez (Print)	
						EDG	
CODE: RW = Rework NIC = Not In Contract ST = Standby WC = Work Cancelled Code - (No. of hours)						Signature of Field Technician	
<b>THE WORK</b> <input checked="" type="checkbox"/> was / <input type="checkbox"/> was not inspected in accordance with the approved documents <b>THE WORK INSPECTED</b> <input checked="" type="checkbox"/> met / <input type="checkbox"/> did not meet the requirements of the approved documents <b>MATERIAL SAMPLING</b> <input type="checkbox"/> was <input type="checkbox"/> was not <input checked="" type="checkbox"/> N/A performed in accordance with the approved documents						07/10/2024	
						Date	Certification Number
						JOB SITE CONTACT IS ASKED TO SIGN TO VERIFY INSPECTION HOURS ONLY THE CONTENT OF THIS REPORT & FEE CHARGES ARE THE RESPONSIBILITY OF OTHERS	
						Signature of Owner-Authorized Job Site Contact	

## DAILY REPORT OF FIELD OBSERVATIONS

**Service Date:** 07/10/2024

**Client:** Pima County

**Project Name:** Rancho Vistoso Valley Vista Sewer Repair

**Project Number:** 608157001

### FIELD OBSERVATION PICTURES



**Excavating trench**