

DAILY REPORT OF FIELD OBSERVATIONS

Service Date: 07/09/2024

Ninyo & Moore

Geotechnical and Environmental Sciences Consultants

1991 East Ajo Way, Suite 145

Tucson AZ 85713

520.577.7600 | www.ninyoandmoore.com

Project Name: Rancho Vistoso Valley Vista Sewer Repair
Project Address: 601 E. Kalalau Dr.
Oro Valley AZ 85755
Client: Pima County
General Contractor: Hunter Contracting
Approved Documents:

Project Number: 608157001
Jurisdiction:
Permit:
Plan File No.

Summary of Field Services:


Arrived on site and talked to Eric on what needed testing.

No density or slurry tests were necessary for today due to finding utilities with pump took longer than planned.

Finished paperwork before leaving site.

Weather: Sunny, Calm, Dry, Low Humidity

SIGNATURES

Start Time	Stop Time	Standard Hours	Overtime Hours	Travel Hours	Total Miles	Edwin Gonzalez (Print)
08:00	15:30	7.5	-	2	35	
CODE: RW = Rework NIC = Not In Contract ST = Standby WC = Work Cancelled Code - (No. of hours)						Signature of Field Technician
THE WORK <input checked="" type="checkbox"/> was / <input type="checkbox"/> was not inspected in accordance with the approved documents THE WORK INSPECTED <input checked="" type="checkbox"/> met / <input type="checkbox"/> did not meet the requirements of the approved documents MATERIAL SAMPLING <input type="checkbox"/> was <input type="checkbox"/> was not <input checked="" type="checkbox"/> N/A performed in accordance with the approved documents						Date
						Certification Number
						JOB SITE CONTACT IS ASKED TO SIGN TO VERIFY INSPECTION HOURS ONLY THE CONTENT OF THIS REPORT & FEE CHARGES ARE THE RESPONSIBILITY OF OTHERS
						Signature of Owner-Authorized Job Site Contact

DAILY REPORT OF FIELD OBSERVATIONS

Service Date: 07/09/2024
Project Name: Rancho Vistoso Valley Vista Sewer Repair

Client: Pima County
Project Number: 608157001

FIELD OBSERVATION PICTURES



Using pump to find utilities



Started with excavation after finding utilities.

DAILY FIELD REPORT

Service Date: 07/09/2024

Ninyo & Moore

Geotechnical and Environmental Sciences Consultants

1991 East Ajo Way, Suite 145
Tucson AZ 85713

520.577.7600 | www.ninyoandmoore.com

Project Name: Rancho Vistoso Valley Vista Sewer Repair

Project Number: 608157001

Project Address: 601 E. Kalalau Dr.
Oro Valley AZ 85755

Client: Pima County

Onsite to pick up:

Pick Up Date/Time: 07/09/2024 02:00 PM

Comments: Procured Slurry samples from 7/8/24 and delivered them to lab.

SAMPLE PHOTOS



Slurry samples from 7/8/24

SIGNATURES

Start Time	Stop Time	Standard Hours	Overtime Hours	Travel Hours	Total Miles	Edwin Gonzalez Name of Technician (Print)
08:00	15:30	7.5	-	2	35	EDG
CODE: RW = Rework NIC = Not In Contract ST = Standby WC = Work Cancelled Code – (No. of hours)						Signature of Technician
THE WORK <input type="checkbox"/> was / <input type="checkbox"/> was not inspected in accordance with the approved documents THE WORK INSPECTED <input type="checkbox"/> met / <input type="checkbox"/> did not meet the requirements of the approved documents MATERIAL SAMPLING <input type="checkbox"/> was <input type="checkbox"/> was not <input type="checkbox"/> N/A performed in accordance with the approved documents						07/09/2024
						Date
						Certification Number
						JOB SITE CONTACT IS ASKED TO SIGN TO VERIFY INSPECTION HOURS ONLY THE CONTENT OF THIS REPORT & FEE CHARGES ARE THE RESPONSIBILITY OF OTHERS
						Signature of Owner-Authorized Job Site Contact