

DAILY FIELD REPORT

Service Date: 07/18/2024

Ninyo & Moore

Geotechnical and Environmental Sciences Consultants

1991 East Ajo Way, Suite 145
Tucson AZ 85713

520.577.7600 | www.ninyoandmoore.com


Project Name: Rancho Vistoso Valley Vista Sewer Repair
Project Address: 601 E. Kalalau Dr.
Oro Valley AZ 85755
Project Number: 608157001
Client: Pima County

Onsite to pick up: Concrete

Pick Up Date/Time: 07/18/2024 07:45 AM

Comments: Arrived on site as requested to pick up 1 set of concrete cylinders cast on 7/17/24.

SIGNATURES

Start Time	Stop Time	Standard Hours	Overtime Hours	Travel Hours	Total Miles	Joel Fimbres Name of Technician (Print)
07:45	08:15	0.5	-	1.5	46	
CODE: RW = Rework NIC = Not In Contract ST = Standby WC = Work Cancelled Code – (No. of hours)						Signature of Technician
THE WORK <input type="checkbox"/> was / <input type="checkbox"/> was not inspected in accordance with the approved documents THE WORK INSPECTED <input type="checkbox"/> met / <input type="checkbox"/> did not meet the requirements of the approved documents MATERIAL SAMPLING <input type="checkbox"/> was <input type="checkbox"/> was not <input type="checkbox"/> N/A performed in accordance with the approved documents						07/18/2024 Date
						Certification Number JOB SITE CONTACT IS ASKED TO SIGN TO VERIFY INSPECTION HOURS ONLY THE CONTENT OF THIS REPORT & FEE CHARGES ARE THE RESPONSIBILITY OF OTHERS
						Signature of Owner-Authorized Job Site Contact