

## DAILY FIELD REPORT

Service Date: 07/25/2024

**Ninyo & Moore**

Geotechnical and Environmental Sciences Consultants

1991 East Ajo Way, Suite 145  
Tucson AZ 85713

520.577.7600 | www.ninyoandmoore.com


**Project Name:** Rancho Vistoso Valley Vista Sewer Repair  
**Project Address:** 601 E. Kalalau Dr.  
Oro Valley AZ 85755  
**Project Number:** 608157001  
**Client:** Pima County

**Onsite to pick up:** Concrete

**Pick Up Date/Time:** 07/25/2024 05:45 PM

**Comments:** Samples picked up and delivered to the lab

### SIGNATURES

| Start Time  | Stop Time | Standard Hours | Overtime Hours | Travel Hours | Total Miles |   |
|---|-----------|----------------|----------------|--------------|-------------|---|
| 17:30   | 18:00     | 0.5            | -              | 1            | 44          | <b>Breanna Espinoza</b><br>Name of Technician (Print)<br>                      |
| <b>CODE:</b> RW = Rework NIC = Not In Contract ST = Standby<br>WC = Work Cancelled Code – (No. of hours)  |           |                |                |              |             | Signature of Technician<br>07/25/2024   |
| <b>THE WORK</b> <input type="checkbox"/> was / <input type="checkbox"/> was not inspected in accordance with the approved documents<br><b>THE WORK INSPECTED</b> <input type="checkbox"/> met / <input type="checkbox"/> did not meet the requirements of the approved documents<br><b>MATERIAL SAMPLING</b> <input type="checkbox"/> was <input type="checkbox"/> was not <input type="checkbox"/> N/A performed in accordance with the approved documents |           |                |                |              |             | Date<br>07/25/2024  |
|   |           |                |                |              |             | Certification Number<br>JOB SITE CONTACT IS ASKED TO SIGN TO VERIFY INSPECTION HOURS ONLY THE CONTENT OF THIS REPORT & FEE CHARGES ARE THE RESPONSIBILITY OF OTHERS |
|   |           |                |                |              |             | Signature of Owner-Authorized Job Site Contact  |